

CA Endeavor SCM 18.1
CA RS 2004 Service List

1

Service	Description	Type
S011104	MIXCASE PASSWORD DOESNT WORK WHEN RACF NOMIXEDCASE OPT IS ON	PTF
S011257	LIST PACKAGE HEADER WITH BASIC FLAG RETURNS WRONG RESPONSE	PTF
S011910	C1U0900E MESSAGE DOES NOT INCLUDE ENVIRONMENT NAME	PTF
S012169	WEB SERVICES & CSV - LOW PRECISION OF LAST UPDATE TIME	PTF
S012300	MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT	PTF
S012301	MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT	PTF
S012308	Q/E BATCH SUBMIT ADDITIONAL JCL PROMPT	PTF
S012312	BC1JXCPY FAILS WITH S806 ABEND	PTF
S012326	(E) JAPANESE LOCALIZATION OF PANELS AND MESSAGES	PTF
S012341	CHMOD CAN FAIL WHEN ISSUED UNDER USERID	PTF
The CA RS 2004 service count for this release is 10		

CA Endeavor SCM
CA RS 2004 Service List for CSIQI10

2

FMID	Service	Description	Type
CSIQI10	S011104	MIXCASE PASSWORD DOESNT WORK WHEN RACF NOMIXEDCASE OPT IS ON	PTF
	S011257	LIST PACKAGE HEADER WITH BASIC FLAG RETURNS WRONG RESPONSE	PTF
	S011910	C1U0900E MESSAGE DOES NOT INCLUDE ENVIRONMENT NAME	PTF
	S012169	WEB SERVICES & CSV - LOW PRECISION OF LAST UPDATE TIME	PTF
	S012300	MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT	PTF
	S012308	Q/E BATCH SUBMIT ADDITIONAL JCL PROMPT	PTF
	S012312	BC1JXCPY FAILS WITH S806 ABEND	PTF
	S012341	CHMOD CAN FAIL WHEN ISSUED UNDER USERID	PTF
The CA RS 2004 service count for this FMID is 8			

CA Endevor SCM
CA RS 2004 Service List for CSIQI11

FMID	Service	Description	Type
CSIQI11	S012301	MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT	PTF
	S012326	(E) JAPANESE LOCALIZATION OF PANELS AND MESSAGES	PTF
The CA RS 2004 service count for this FMID is 2			

Service	Details				
SO11104	<p>SO11104 M.C.S. ENTRIES = ++PTF (SO11104)</p> <p>MIXCASE PASSWORD DOESNT WORK WHEN RACF NOMIXEDCASE OPT IS ON</p> <p>PROBLEM DESCRIPTION:</p> <p>Customers cannot access new versions of the Eclipse UI with a lowercase or mixedcase password when they have RACF as security product and the NOMIXEDCASE option is on.</p> <p>New Eclipse versions perform a REST /auth request after inserting the userID and password to verify that everything is setup properly. The code flow for this request is new, i.e. it does not use the same logic as other REST calls. Endevor code to uppercase the password when NOMIXEDCASE option is on for RACF is not in place for /auth requests and RACF does not uppercase the password automatically, which is generating the issue.</p> <p>SYMPTOMS:</p> <p>The message credentials or password invalid is triggered.</p> <p>IMPACT:</p> <p>The customer cannot use Eclipse UI with a lower or mix cased password.</p> <p>CIRCUMVENTION:</p> <p>Use an uppercase password if RACF is the security product and NOMIXEDCASE option is on.</p> <p>PRODUCT(S) AFFECTED:</p> <table> <tr> <td>CA Endevor SCM</td><td>Version 18.0</td></tr> <tr> <td>CA Endevor SCM</td><td>Release 18.1</td></tr> </table> <p>Related Problem:</p> <p>ENDBAS 7745</p> <p>Copyright (C) 2019 CA. All rights reserved. R00011-SCM181-SP0</p> <p>DESC(MIXCASE PASSWORD DOESNT WORK WHEN RACF NOMIXEDCASE OPT IS ON).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST11104)</p>	CA Endevor SCM	Version 18.0	CA Endevor SCM	Release 18.1
CA Endevor SCM	Version 18.0				
CA Endevor SCM	Release 18.1				

Service	Details						
SO11257	<p>SO11257 M.C.S. ENTRIES = ++PTF (SO11257)</p> <p>LIST PACKAGE HEADER WITH BASIC FLAG RETURNS WRONG RESPONSE</p> <p>PROBLEM DESCRIPTION:</p> <p>The List Package Header Basic Response fields are populated incorrectly when the List Package Header Request Flag is set to 'B' (basic). The flag is not taken into consideration when populating the response block and the Full version of the block is always used, which has different offsets for most of the fields than the basic response block. As a result, basic response fields have incorrect (shifted) values.</p> <p>SYMPTOMS:</p> <p>The Basic Response fields do not return the correct values.</p> <p>IMPACT:</p> <p>The customer cannot get package header basic information.</p> <p>CIRCUMVENTION:</p> <p>Use the Full Response fields to extract the information.</p> <p>PRODUCT(S) AFFECTED:</p> <table> <tr> <td>CA Endeavor SCM</td><td>Version 17.0</td></tr> <tr> <td>CA Endeavor SCM</td><td>Version 18.0</td></tr> <tr> <td>CA Endeavor SCM</td><td>Version 18.1</td></tr> </table> <p>Related Problem:</p> <p>ENDBAS 7746</p> <p>Copyright (C) 2019 CA. All rights reserved. R00013-SCM181-SP0</p> <p>DESC (LIST PACKAGE HEADER WITH BASIC FLAG RETURNS WRONG RESPONSE).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST11257)</p>	CA Endeavor SCM	Version 17.0	CA Endeavor SCM	Version 18.0	CA Endeavor SCM	Version 18.1
CA Endeavor SCM	Version 17.0						
CA Endeavor SCM	Version 18.0						
CA Endeavor SCM	Version 18.1						

Service	Details				
SO11910	<p>SO11910 M.C.S. ENTRIES = ++PTF (SO11910)</p> <p>C1U0900E MESSAGE DOES NOT INCLUDE ENVIRONMENT NAME</p> <p>PROBLEM DESCRIPTION:</p> <p>Message C1U0900E shows up when a non-package action is attempted against an inventory area which has a related approver group to indicate that package processing is required. The message shows the stage, system, subsystem and type from the involved inventory area, but is missing the environment name.</p> <p>SYMPTOMS:</p> <p>The message C1U0900E lacks the environment information.</p> <p>IMPACT:</p> <p>Client unable to extract environment information from the C1U0900E message.</p> <p>CIRCUMVENTION:</p> <p>None.</p> <p>PRODUCT(S) AFFECTED:</p> <table> <tr> <td>CA Endeavor SCM</td><td>Version 18.0</td></tr> <tr> <td>CA Endeavor SCM</td><td>Version 18.1</td></tr> </table> <p>Related Problem:</p> <p>ENDBAS 7759</p> <p>Copyright (C) 2020 CA. All rights reserved. R00024-SCM181-SP0</p> <p>DESC(C1U0900E MESSAGE DOES NOT INCLUDE ENVIRONMENT NAME).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST11910)</p>	CA Endeavor SCM	Version 18.0	CA Endeavor SCM	Version 18.1
CA Endeavor SCM	Version 18.0				
CA Endeavor SCM	Version 18.1				

CA Endeavor SCM 18.1
CA RS 2004 - PTF SO12169 Details

7

Service	Details
SO12169	<p>SO12169 M.C.S. ENTRIES = ++PTF (SO12169)</p> <p>WEB SERVICES & CSV - LOW PRECISION OF LAST UPDATE TIME</p> <p>PROBLEM DESCRIPTION:</p> <p>In List Element Components CSV requested via the CSV utility, and by extension also in the REST API Element endpoint with data=ele, the last change time (CHG TIME in csv, chDate in rest api response) has lower precision than the corresponding field in list element output - minutes instead of hundreds of seconds) causing problems for clients wanting to compare these values</p> <p>SYMPTOMS:</p> <p>See description</p> <p>IMPACT:</p> <p>Using last change time from element summary to identify a version of the source is less reliable - has to only match hours and minutes. This was an issue for the new Eclipse UI merge feature.</p> <p>CIRCUMVENTION:</p> <p>Compare the fields only up to minutes</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7767</p> <p>Copyright (C) 2020 CA. All rights reserved. R00027-SCM181-SP0</p> <p>DESC(WEB SERVICES & CSV - LOW PRECISION OF LAST UPDATE TIME).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST12169)</p>

Service	Details
SO12300	<div>SO12300 M.C.S. ENTRIES = ++PTF (SO12300)</div> <div>MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT</div> <div>PROBLEM DESCRIPTION:</div> <div>When enabling MFA Support, it is not possible to check if it has been done correctly. The value is not shown in either EN\$TROPT or the SITE panel.</div> <div>SYMPTOMS:</div> <div>The EN\$TROPT and SITE panel C1SES000 are not showing any information regarding the status of MFA support.</div> <div>IMPACT:</div> <div>The user cannot check if the MFA Support has been correctly enabled.</div> <div>CIRCUMVENTION:</div> <div>1) Invoke any Endeavor ISPF interface</div> <div>2) Issue the following command based on your release:</div> <div><div>- for V18: TSO ISRDDN B C1DEFLT\$+108</div><div>- for V18.1: TSO ISRDDN B C1DEFLT\$+109</div></div> <div>3) The MFAAPPL value will appear on the first line (the text part on the right side)</div> <div>PRODUCT AFFECTED:</div> <div>CA Endeavor Software Change Manager, Version 18.0</div> <div>CA Endeavor Software Change Manager, Version 18.1</div> <div>Related Problem:</div> <div>ENDBAS 7761</div> <div>Copyright (C) 2020 CA. All rights reserved. R00030-SCM181-SP0</div> <div>DESC(MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT) .</div> <div>++VER (Z038)</div> <div>FMID (CSIQI10)</div> <div>PRE (SO11495)</div> <div>SUP (ST12300)</div> <div>++IF FMID(CSIQI11) REQ(SO12301) .</div> <div>++HOLD (SO12300) SYSTEM FMID(CSIQI10)</div> <div>REASON (ACTION) DATE (20070)</div> <div>COMMENT (</div> <div><div><div>CA Endeavor SCM</div><div>Release 18.1</div></div></div> <div><div>SEQUENCE</div><div>Before Apply</div></div> <div><div>PURPOSE</div><div>This PTF updates PANELS in the CSIQPENU library.</div><div>If you have customized the PANEL(S) delivered by this PTF,</div><div>you must backup your customized version of the PANEL(S)</div><div>before applying this PTF to avoid losing your changes.</div></div> <div><div>USERS</div><div>All Endeavor users.</div></div> <div><div>AFFECTED</div><div></div></div> <div><div>KNOWLEDGE</div><div>1. SMP/e</div></div> <div><div>REQUIRED</div><div>2. Endeavor Administration</div><div>3. Endeavor PANELS</div></div> <div><div>ACCESS</div><div>No special access is required.</div></div> <div><div>REQUIRED</div><div></div></div>

CA Endeavor SCM 18.1
CA RS 2004 - PTF SO12300 Details

Service	Details
	<pre>+-----+-----+ ***** * STEPS TO PERFORM * ***** 1. Backup any customized PANELS in CSIQPENU that this PTF supplies. 2. APPLY this PTF. 3. Re-apply your customizations to the updated PANELS in CSIQPENU.).</pre>

Service	Details
SO12301	<div>SO12301 M.C.S. ENTRIES = ++PTF (SO12301)</div> <div>MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT</div> <div>PROBLEM DESCRIPTION:</div> <div>When enabling MFA Support, it is not possible to check if it has been done correctly. The value is not shown in either EN\$TROPT or the SITE panel.</div> <div>SYMPTOMS:</div> <div>The EN\$TROPT and SITE panel C1SES000 are not showing any information regarding the status of MFA support.</div> <div>IMPACT:</div> <div>The user cannot check if the MFA Support has been correctly enabled.</div> <div>CIRCUMVENTION:</div> <div>1) Invoke any Endeavor ISPF interface</div> <div>2) Issue the following command based on your release:</div> <div>- for V18: TSO ISRDDN B C1DEFLTS+108</div> <div>- for V18.1: TSO ISRDDN B C1DEFLTS+109</div> <div>3) The MFAAPPL value will appear on the first line (the text part on the right side)</div> <div>PRODUCT AFFECTED:</div> <div>CA Endeavor Software Change Manager, Version 18.0</div> <div>CA Endeavor Software Change Manager, Version 18.1</div> <div>Related Problem:</div> <div>ENDBAS 7761</div> <div>Copyright (C) 2020 CA. All rights reserved. R00030-SCM181-SP0</div> <div>DESC(MISSING MFA INFORMATION FROM SITE PANEL AND EN\$TROPT) .</div> <div>++VER (Z038)</div> <div>FMID (CSIQI11)</div> <div>SUP (ST12301)</div> <div>++IF FMID(CSIQI10) REQ(SO12300) .</div> <div>++HOLD (SO12301) SYSTEM FMID(CSIQI11)</div> <div>REASON (ACTION) DATE (20070)</div> <div>COMMENT (</div> <div>+-----</div>

Service	Details
	***** * STEPS TO PERFORM * ***** 1. Backup any customized PANELS in CSIQPJPN that this PTF supplies. 2. APPLY this PTF. 3. Re-apply your customizations to the updated PANELS in CSIQPJPN.).

CA Endeavor SCM 18.1
CA RS 2004 - PTF SO12308 Details

12

Service	Details
SO12308	<p>SO12308 M.C.S. ENTRIES = ++PTF (SO12308)</p> <p>Q/E BATCH SUBMIT ADDITIONAL JCL PROMPT</p> <p>PROBLEM DESCRIPTION:</p> <p>After applying SO12079 - Quick Edit no longer prompts for additional JCL if Include Additional JCL is set to 'Y'.</p> <p>SYMPTOMS:</p> <p>Panel ENDIE710 to request additional JCL is bypassed, however, previously saved additional JCL is included in the job.</p> <p>IMPACT:</p> <p>Quick Edit users with Quick Edit Batch Action Queue feature enabled cannot edit additional JCL when submitting a single (non-queued) request.</p> <p>CIRCUMVENTION:</p> <p>Instead of submitting the request directly, enable the Queue option and then use SQ command to submit the Queue - the Include Additional JCL works as expected then.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7774</p> <p>Copyright (C) 2020 CA. All rights reserved. R00031-SCM181-SP0</p> <p>DESC(Q/E BATCH SUBMIT ADDITIONAL JCL PROMPT).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>PRE (SO11288 SO12079)</p> <p>SUP (ST12308)</p>

Service	Details
SO12312	<p>SO12312 M.C.S. ENTRIES = ++PTF (SO12312)</p> <p>BC1JXCPY FAILS WITH S806 ABEND</p> <p>PROBLEM DESCRIPTION:</p> <p>Using the JCL code provided in the BC1JXCPY sample job results in a S806 abend when trying to run the BSTXCOPY utility.</p> <p>SYMPTOMS:</p> <p>The S806 abend is returned.</p> <p>IMPACT:</p> <p>Members cannot be copied from PDS/E to PDS/E.</p> <p>CIRCUMVENTION:</p> <p>Correct the SCMM@LIB member by including the CSIQLOAD library in the STEPLIB and authorize this library. Or update the BC1JXCPY sample job by including STEPLIB with CSIQAUTU, CSIQAUTH and CSIQLOAD and removing the include SCMM@LIB statement.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Version 18.0</p> <p>CA Endeavor SCM Version 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7775</p> <p>Copyright (C) 2020 CA. All rights reserved. R00033-SCM181-SP0</p> <p>DESC(BC1JXCPY FAILS WITH S806 ABEND).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST12312)</p> <p>++HOLD (SO12312) SYSTEM FMID(CSIQI10)</p> <p>REASON (ACTION) DATE (20071)</p> <p>COMMENT (</p> <pre> +-----+ CA Endeavor SCM Release 18.1 +-----+ SEQUENCE Before Apply +-----+ PURPOSE This PTF updates JCL in the CSIQJCL library. If you have customized versions of the JCL(S) in CSIQJCL, you must make a backup copy of them BEFORE applying this PTF to avoid losing your changes. +-----+ USERS All Endeavor users. AFFECTED +-----+ KNOWLEDGE 1. SMP/e REQUIRED 2. Endeavor Product Administration +-----+ ACCESS No special access required. REQUIRED +-----+ ***** * STEPS TO PERFORM * ***** 1. Backup any customized JCL in CSIQJCL that this PTF supplies. 2. APPLY this PTF. </pre>

CA Endeavor SCM 18.1
CA RS 2004 - PTF SO12312 Details

14

Service	Details
	3. Re-apply your customizations to the updated JCL in CSIQJCL.).

Service	Details
SO12326	<p>SO12326 M.C.S. ENTRIES = ++PTF (SO12326)</p> <p>(E) JAPANESE LOCALIZATION OF PANELS AND MESSAGES</p> <p>ENHANCEMENT DESCRIPTION:</p> <p>This Enhancement delivers panels and messages that have been translated from English to Japanese, ensuring that the Japanese version of the product is in sync with the English version.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Version 18.0</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7758</p> <p>Copyright (C) 2020 CA. All rights reserved. R00034-SCM181-SP0</p> <p>DESC((E) JAPANESE LOCALIZATION OF PANELS AND MESSAGES).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI11)</p> <p>PRE (SO11289)</p> <p>SUP (ST11708 ST11884 ST12326)</p> <p>++IF FMID(CSIQI10) REQ(SO11288 SO12079) .</p> <p>++HOLD (SO12326) SYSTEM FMID(CSIQI11)</p> <p>REASON (ACTION) DATE (20072)</p> <p>COMMENT (</p> <pre> +-----+ CA Endeavor SCM Japanese Localization Release 18.1 +-----+-----+ SEQUENCE Before Apply +-----+-----+ PURPOSE This PTF updates PANELS in the CSIQPJPN library. If you have customized the PANEL(S) delivered by this PTF, you must backup your customized version of the PANEL(S) before applying this PTF to avoid losing your changes. +-----+-----+ USERS All Endeavor users. AFFECTED +-----+-----+ KNOWLEDGE 1. SMP/e REQUIRED 2. Endeavor Administration 3. Endeavor PANELS +-----+-----+ ACCESS No special access is required. REQUIRED +-----+-----+ ***** * STEPS TO PERFORM * ***** 1. Backup any customized PANELS in CSIQPJPN that this PTF supplies. 2. APPLY this PTF. 3. Re-apply your customizations to the updated PANELS in CSIQPJPN.).</pre>

Service	Details	
SO12341	SO12341 M.C.S. ENTRIES = ++PTF (SO12341)	
	CHMOD CAN FAIL WHEN ISSUED UNDER USERID	
	PROBLEM DESCRIPTION:	
	In cases where a USS file is being written, a CHMOD may be attempted under the context of the USERID and will fail if the user does not have authority to execute the command.	
	SYMPTOMS:	
	An error message is issued when retrieving an element to a USS directory if the user does not have access to submit the CHMOD command.	
	IMPACT:	
	The element is retrieved but an error is issued and the action gets a return code of 12, which may affect other Endeavor processing.	
	CIRCUMVENTION:	
	Perform the retrieve action with a USERID that has access to perform the CHMOD command.	
	PRODUCT(S) AFFECTED:	
	CA Endeavor SCM	Version 18.0
	CA Endeavor SCM	Release 18.1
	Related Problem:	
	ENDBAS 7771	
	Copyright (C) 2020 CA. All rights reserved. R00035-SCM181-SP0	
	DESC(CHMOD CAN FAIL WHEN ISSUED UNDER USERID) .	
	++VER (Z038)	
	FMID (CSIQI10)	
	SUP (ST12341)	
	MCS SO11104	STARTS ON PAGE 0002
	MCS SO11257	STARTS ON PAGE 0002
	MCS SO11910	STARTS ON PAGE 0003
	MCS SO12169	STARTS ON PAGE 0004
	MCS SO12300	STARTS ON PAGE 0005
	MCS SO12301	STARTS ON PAGE 0006
	MCS SO12308	STARTS ON PAGE 0008
	MCS SO12312	STARTS ON PAGE 0009
	MCS SO12326	STARTS ON PAGE 0010
	MCS SO12341	STARTS ON PAGE 0012

CA Endevor SCM 18.1
CA RS 2004 Product/Component Listing

17

Product Family	Product	Release
Application Development	CA ENDEVOR SCM	18.01.00
The CA RS 2004 Product/Component Count for this release is 1		

CA RS Level	Service	FMID
CAR2004	S012341	CSIQI10
	S012326	CSIQI11
	S012312	CSIQI10
	S012308	CSIQI10
	S012301	CSIQI11
	S012300	CSIQI10
	S012169	CSIQI10
	S011910	CSIQI10
	S011257	CSIQI10
	S011104	CSIQI10
CAR2003	S012079	CSIQI10
	S011879	CSIQI10
	S011289	CSIQI11
	S011288	CSIQI10
CAR2002	S011541	CSIQI10
	S011495	CSIQI10
	S011467	CSIQI13
	S011272	CSIQI13
CAR2001	S011124	CSIQI11
	S011123	CSIQI10
	S010979	CSIQI10
	S010896	CSIQI10
	S010825	CSIQI13
	S010824	CSIQI10
	S010822	CSIQI10