

CA Endeavor SCM 18.1
CA RS 2006 Service List

Service	Description	Type
S012864	SUPPORT NDVRC1 IN TASKLIB/TSOLIB	PTF
S012961	STORAGE LEAK IN WEB SERVICES STC	PTF
S013068	REPORT JOBID WHEN SUBMITTING A PACKAGE	PTF
S013128	SUPPORT CHANGING C1DEFLT5 IN TSO CLIENT	PTF
S013177	INTEGRITY PROBLEM	PTF
The CA RS 2006 service count for this release is 5		

CA Endeavor SCM
CA RS 2006 Service List for CSIQI10

2

FMID	Service	Description	Type
CSIQI10	S012864	SUPPORT NDVRC1 IN TASKLIB/TSOLIB	PTF
	S012961	STORAGE LEAK IN WEB SERVICES STC	PTF
	S013068	REPORT JOBID WHEN SUBMITTING A PACKAGE	PTF
	S013128	SUPPORT CHANGING C1DEFLT5 IN TSO CLIENT	PTF
	S013177	INTEGRITY PROBLEM	PTF
The CA RS 2006 service count for this FMID is 5			

Service	Details				
SO12864	<p>SO12864 M.C.S. ENTRIES = ++PTF (SO12864)</p> <p>SUPPORT NDVRC1 IN TASKLIB/TSOLIB</p> <p>PROBLEM DESCRIPTION:</p> <p>Some customers would like to run Endeavor using TASKLIB rather than from STEPLIB or LINKLIST/LPA. This solution adds support for these situations.</p> <p>SYMPTOMS:</p> <p>If Endeavor is not executing from STEPLIB or LINKLIST initialization may fail with messages like:</p> <p>BC1PROUT: E0003 BC1PROUT MSGP ERROR - NO RESPONSE FROM BC1PSERV</p> <p>IMPACT:</p> <p>Any customer running Endeavor using TSOLIB or dynamic TASKLIB routines may fail to complete initialisation.</p> <p>CIRCUMVENTION:</p> <p>Make sure Endeavor load modules can be accessed from STEPLIB or LINKLIST as documented in the install guide.</p> <p>PRODUCT(S) AFFECTED:</p> <table> <tr> <td>CA Endeavor SCM</td><td>Release 18.0</td></tr> <tr> <td>CA Endeavor SCM</td><td>Release 18.1</td></tr> </table> <p>Related Problem:</p> <p>ENDBAS 7786</p> <p>Copyright (C) 2020 CA. All rights reserved. R00046-SCM181-SP0</p> <p>DESC(SUPPORT NDVRC1 IN TASKLIB/TSOLIB).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>PRE (SO11879 SO12490)</p> <p>SUP (ST12864)</p>	CA Endeavor SCM	Release 18.0	CA Endeavor SCM	Release 18.1
CA Endeavor SCM	Release 18.0				
CA Endeavor SCM	Release 18.1				

CA Endeavor SCM 18.1
CA RS 2006 - PTF SO12961 Details

Service	Details
SO12961	<p>SO12961 M.C.S. ENTRIES = ++PTF (SO12961)</p> <p>STORAGE LEAK IN WEB SERVICES STC</p> <p>PROBLEM DESCRIPTION:</p> <p>A web services started task (STC) runs into abends after its been used for a while. The abends seen so far are S878-10, S80A and U3009. If and when an abend occurs depends on how intensive the STC is used and timeout settings.</p> <p>SYMPTOMS:</p> <p>Abend: S878-10, S80A or U3009.</p> <p>IMPACT:</p> <p>The STC becomes unusable. Client requests fail.</p> <p>CIRCUMVENTION:</p> <p>Restart the STC frequently. This can be accomplished in 2 ways:</p> <ol style="list-style-type: none"> 1. update STC pooling parameters <p>Change these parameters in the web services configuration file:</p> <ul style="list-style-type: none"> - PoolReapTime: the interval (in seconds) for running the STC pool monitoring thread. - AgedTimeout: the number of seconds that an STC connection can remain active. <p>PoolReapTime must be lower than AgedTimeout and determines the precision of AgedTimeout.</p> <p>Example:</p> <p>AgedTimeout 1800 (30 minutes and PoolReapTime 60 (1 minute) means that an STC will end after 29-30 minutes.</p> <ol style="list-style-type: none"> 2. disable STC pooling <p>This approach results in longer response times.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7783</p> <p>Copyright (C) 2020 CA. All rights reserved. R00049-SCM181-SP0</p> <p>DESC (STORAGE LEAK IN WEB SERVICES STC).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>PRE (S011495 S012300)</p> <p>SUP (ST12803 ST12961)</p>

CA Endeavor SCM 18.1
CA RS 2006 - PTF SO13068 Details

5

Service	Details				
SO13068	<p>SO13068 M.C.S. ENTRIES = ++PTF (SO13068)</p> <p>REPORT JOBID WHEN SUBMITTING A PACKAGE</p> <p>PROBLEM DESCRIPTION:</p> <p>Submit Package action in batch and Endeavor API does not return the job id of the submitted job, making it more difficult to identify the submitted job. This PTF adds a new message ENMP083I to C1MSGs1 with the jobid of the submitted job.</p> <p>SYMPTOMS:</p> <p>See description</p> <p>IMPACT:</p> <p>Caller of Submit Package may not be able to reliably identify which job was submitted by a submit package action.</p> <p>CIRCUMVENTION:</p> <p>Use the combination of job name and submission time to identify the job</p> <p>PRODUCT(S) AFFECTED:</p> <table> <tr> <td>CA Endeavor SCM</td><td>Release 18.0</td></tr> <tr> <td>CA Endeavor SCM</td><td>Release 18.1</td></tr> </table> <p>Related Problem:</p> <p>ENDBAS 7785</p> <p>Copyright (C) 2020 CA. All rights reserved. R00051-SCM181-SP0</p> <p>DESC(REPORT JOBID WHEN SUBMITTING A PACKAGE).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>SUP (ST12957 ST13068)</p>	CA Endeavor SCM	Release 18.0	CA Endeavor SCM	Release 18.1
CA Endeavor SCM	Release 18.0				
CA Endeavor SCM	Release 18.1				

CA Endeavor SCM 18.1
CA RS 2006 - PTF SO13128 Details

6

Service	Details
SO13128	<p>SO13128 M.C.S. ENTRIES = ++PTF (SO13128)</p> <p>SUPPORT CHANGING C1DEFLT5 IN TSO CLIENT</p> <p>ENHANCEMENT DESCRIPTION:</p> <p>C1DEFLT5 CAN BE CHANGED IN TSO AFTER EXITING ALL ACTIVE ENDEVOR INSTANCES.</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7788</p> <p>Copyright (C) 2020 CA. All rights reserved. R00052-SCM181-SP0</p> <p>DESC(SUPPORT CHANGING C1DEFLT5 IN TSO CLIENT).</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>PRE (SO11495 SO11879 SO12490 SO13177)</p> <p>SUP (SO12498 SO12864 ST12498 ST12864 ST13128)</p>

CA Endeavor SCM 18.1
CA RS 2006 - PTF S013177 Details

7

Service	Details
S013177	<p>S013177 M.C.S. ENTRIES = ++PTF (S013177)</p> <p>INTEGRITY PROBLEM</p> <p>PROBLEM DESCRIPTION:</p> <p>Integrity Problem.</p> <p>SYMPTOMS:</p> <p>N/A</p> <p>IMPACT:</p> <p>Integrity Problem</p> <p>CIRCUMVENTION:</p> <p>N/A</p> <p>PRODUCT(S) AFFECTED:</p> <p>CA Endeavor SCM Release 18.1</p> <p>Related Problem:</p> <p>ENDBAS 7778</p> <p>Copyright (C) 2020 CA. All rights reserved. R00053-SCM181-SP0</p> <p>DESC (INTEGRITY PROBLEM) .</p> <p>++VER (Z038)</p> <p>FMID (CSIQI10)</p> <p>PRE (S011495 S012490)</p> <p>SUP (ST12919 ST13177)</p>

CA Endevor SCM 18.1
CA RS 2006 Product/Component Listing

Product Family	Product	Release
Application Development	CA ENDEVOR SCM	18.01.00
The CA RS 2006 Product/Component Count for this release is 1		

CA Endeavor SCM 18.1
All CA RS Levels Service List

CA RS Level	Service	FMID
CAR2006	S013177	CSIQI10
	S013128	CSIQI10
	S013068	CSIQI10
	S012961	CSIQI10
	S012864	CSIQI10
CAR2005	S012574	CSIQI13
	S012546	CSIQI10
	S012498	CSIQI10
	S012495	CSIQI11
	S012494	CSIQI10
	S012491	CSIQI13
	S012490	CSIQI10
	S012309	CSIQI13
	S012022	CSIQI10
CAR2004	S012341	CSIQI10
	S012326	CSIQI11
	S012312	CSIQI10
	S012308	CSIQI10
	S012301	CSIQI11
	S012300	CSIQI10
	S012169	CSIQI10
	S011910	CSIQI10
	S011257	CSIQI10
	S011104	CSIQI10
CAR2003	S012079	CSIQI10
	S011879	CSIQI10
	S011289	CSIQI11
	S011288	CSIQI10
CAR2002	S011541	CSIQI10
	S011495	CSIQI10
	S011467	CSIQI13
	S011272	CSIQI13
CAR2001	S011124	CSIQI11
	S011123	CSIQI10
	S010979	CSIQI10
	S010896	CSIQI10
	S010825	CSIQI13
	S010824	CSIQI10
	S010822	CSIQI10