MIM Resource Sharing 12.5 CA RS 2204 Service List

Service	Description	Type
LU01493	MIM0355W DURING STARTUP	PTF
LU03454	NON-MANAGED ENQS NOT COUNTED	PTF
LU04830	SHUTDOWN FREE NOT WORKING	PTF
LU05137	IEC9991 ERROR MESSAGE DURING MIM SHUTDOWN	PTF
LU05244	MIM CTC I/O DELAY	PTF
The CA RS 2204 service count for this release is 5		

MIM Resource Sharing CA RS 2204 Service List for CBTDC50

FMID	Service	Description	Type
CBTDC50	LU01493	MIMO355W DURING STARTUP	PTF
	LU03454	NON-MANAGED ENQS NOT COUNTED	PTF
	LU04830	SHUTDOWN FREE NOT WORKING	PTF
	LU05137	IEC999I ERROR MESSAGE DURING MIM SHUTDOWN	PTF
	LU05244	MIM CTC I/O DELAY	PTF
The CA RS 2204 service count for this FMID is 5			

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU01493 Details

Service	Details
	LU01493 M.C.S. ENTRIES = ++PTF (LU01493)
2001130	Zoolise More Zhinize
	MIMO355W DURING STARTUP
	PROBLEM DESCRIPTION:
	A system mask in the MIM control file which represents FREED systems
	in the MIMPLEX may be incorrect.
	SYMPTOMS:
	There are 2 different cases which can occur:
	Case 1:
	> MIMINIT COMMUNICATION=XCF/CTCONLY
	> INITIAL=FREED coded on the DEFSYS statement
	> New checkpoint file(s) were allocated
	The first system in the MIMPLEX is started with FORMAT=NONE.
	The following message will be seen in the MIMLOG:
	MIM0300I Checkpoint File Status 889
	Id Volser Status Format-Action
	00 vvvvvv IN-USE Formatted On Error
	A DISPLAY SYSTEMS command will show systems with a "NOPATH"
	status:
	MIMO108I SYSTEMS DISPLAY
	INDEX ALIAS SYSTEM RELATION STATUS OPSYS LAST ACCESS
	01 03 SYSA LOCAL STARTED zOS yyyy.ddd tt:tt:tt.tt
	02 13 SYSB EXTERNAL NOPATH
	03 62 SYSC EXTERNAL NOPATH
	If COMMUNICATON=CTCONLY, the local starting system will synchronize.
	If COMMUNICATION=XCF, the local starting system will not synchronize.
	MIM will repeatedly issue the following message: MIMO355W Initialization cannot continue until an eligible MASTER
	becomes available
	Case 2:
	> MIMINIT COMMUNICATION=XCF/CTCONLY
	> INITIAL=FREED coded on the DEFSYS statement
	> The checkpoint file was not pristine. It contains
	old systems not on the current DEFSYS statement.
	> The first system in the MIMPLEX is started with FORMAT=CHKPT.
	> The local system will not synchronize.
	If COMMUNICATION=XCF:
	CA MIM will issue the following message repeatedly during startup:
	MIM0355W Initialization cannot continue until an eligible MASTER
	becomes available
	If COMMUNICATION=CTCONLY:
	CA MIM will issue the following message and not proceed any
	further:
	MIM0331I system ssss VCF initialization PENDING
	IMPACT:
	If the local starting system does not synchronize,
	global messages/commands, tape allocations, and ENQs will not
	be processed. If the Early Start Mechanism is being used, the
	system will not complete the IPL.
	CIRCUMVENTION:
	For Case #1, enter a FREE command for all external systems that are not active.
	For Case #2, restart MIM with FORMAT=BOTH on the first system and FORMAT=CHKPT on the remaining systems.
	and Format-Chart on the remaining systems.

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU01493 Details

Service	De	etails
	PRODUCT(S) AFFECTED:	
	CA MULTI-IMAGE MANAGER	Release 12.5
	Related Problem:	
	MIM 13824	
	(C) 2022 Broadcom Inc and/or its sul	bsidiaries; All rights reserved
	R00144-BTD125	
	DESC(MIM0355W DURING STARTUP).	
	++VER (Z038)	
	FMID (CBTDC50)	
	PRE (LU04830 LU04915 R090745 R09202	25 R095758 S001314
	S004180 S005399 S006020 S007592)	
	SUP (LT01493)	

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU03454 Details

Service	Details
LU03454	LU03454 M.C.S. ENTRIES = ++PTF (LU03454)
	NON-MANAGED ENQS NOT COUNTED
	PROBLEM DESCRIPTION:
	GDIF's GRS exits may not be called for certain non-managed
	ENQ requests.
	The issue can occur if the SET GDIF COUNT option is changed
	via an operator command. The following option changes show
	which ENQs may not be counted:
	From RESERVES to SYSTEMS (SYSTEMS ENQs may not be counted)
	From RESERVES to ALL (SYSTEMS and SYSTEM ENQs may not be counted)
	From SYSTEMS to ALL (SYSTEM enqs may not be counted)
	SYMPTOMS:
	SCOPE=SYSTEM/SYSTEMS ENQs may be missing from the non-managed
	portion of the DISPLAY COUNTS command output.
	IMPACT:
	No impact.
	CIRCUMVENTION:
	Enter the ADDQNAME command for an non-existent qname. For example:
	F MIM, ADDQNAME QNAME=DUMMYXYZ
	The command only needs to be entered on one system in each
	MIMPLEX.
	Or, restart GDIF after changing SET GDIF COUNT to the
	desired value.
	PRODUCT(S) AFFECTED:
	CA MULTI-IMAGE MANAGER Release 12.5
	Related Problem:
	MII 15271
	(C) 2022 Broadcom Inc and/or its subsidiaries; All rights reserved
	R00149-BTD125
	DESC (NON-MANAGED ENQS NOT COUNTED).
	++VER (Z038)
	FMID (CBTDC50)
	PRE (LU04915)
	SUP (LT03454)

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU04830 Details

Service	Details
LU04830	LU04830 M.C.S. ENTRIES = ++PTF (LU04830)
	SHUTDOWN FREE NOT WORKING
	PROBLEM DESCRIPTION:
	1> CA MIM may delete the transaction that is created as a result of
	the SHUTDOWN FREE command. The transaction is used to notify the
	external systems to FREE the local system from the MIMPLEX.
	2> CA MIM may not populate the FREED status to a physical
	control file, if a SHUTDOWN FREE command is entered before a
	control file migration completes.
	SYMPTOMS:
	 1> A SHUTDOWN FREE command was entered on a system that was in
	the process of migrating to a physical control file (DASD or
	list structure).
	The system was marked STOPPED but not FREED.
	DISPLAY SYSTEMS may show:
	INDEX ALIAS SYSTEM RELATION STATUS OPSYS LAST ACCESS
	01
	02 02 SYSB EXTERNAL STOPPED zOS 2021.243 11:17:29.67
	03
	04 04 SYSD EXTERNAL FREED
	05 05 SYSE EXTERNAL FREED
	06
	In the previous display, the SHUTDOWN FREE command was entered
	on SYSB.
	ENQs and tape devices that were allocated on the STOPPED system
	will not be available to other systems.
	The STOPPED status can also impact a restart after a global
	shutdown. The MIMPLEX will not synchronize and the
	following messages may be issued.
	MIMO350W system SYSB has not responded to VCF communication
	MIMO061W System SYSB in file nn - inoperative due to SHUTDOWN
	2> A non fatal U0095 RC=98 abend may be generated. Or, the
	system that was SHUT FREE'd will show as MIGRATING in the DISPLAY
	SYSTEMS command output.
	IMPACT:
	If the MIMPLEX is not synchronized after a restart:
	> Tape drives will not be brought online.
	> Global ENQs will not be processed.
	> Cross system messages will not be collected.
	If a system shows as MIGRATING but is not longer active, the
	migration event will not complete. This could cause global enqs,
	tape allocations, and messages to suspend.
	The U0095 RC=98 abend should have no impact other than an SVC dump
	being produced.
	CIRCUMVENTION:
	These issues can be prevented by waiting until the migration completes
	and then entering the SHUTDOWN FREE command.
	If a starting system won't synchronize due to a system showing
	as STOPPED in the DISPLAY SYSTEMS output, simply enter
	the FREE command for the affected system(s). Or start
	the affected system(s).
	If a system shows as MIGRATING but is down, enter a FREE command

for that system.

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU04830 Details

Service	Details
	PRODUCT(S) AFFECTED:
	CA MULTI-IMAGE MANAGER Release 12.5
	Related Problem:
	MIM 14673
	(C) 2022 Broadcom Inc and/or its subsidiaries; All rights reserved
	R00151-BTD125
	DESC(SHUTDOWN FREE NOT WORKING).
	++VER (Z038)
	FMID (CBTDC50)
	PRE (LU01392 LU02532 LU04915 R090745 R092025 R095758
	R097775 S001276 S001314 S004131 S004180 S005399
	S006020 S006490 S007592 S008521 S010843 S013054)
	SUP (LT04830 R093502 R096406 R096418 S005973 S008268
	S010280 S010614 ST05973 ST08268 ST10280 ST10614
	TR93502 TR96404 TR96406 TR96418)
	CSECT (MIMDRCMD MIMDRCNM).

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU05137 Details

Service	Details
LU05137	LU05137 M.C.S. ENTRIES = ++PTF (LU05137)
	IEC999I ERROR MESSAGE DURING MIM SHUTDOWN
	PROBLEM DESCRIPTION:
	CA MIM may open the same DCB twice for MIMLOG/MIMTRC if started before
	JES.
	This can happen if the ADDLOG command for MIMLOG or MIMTRC is
	directed to a dataset or NULLFILE.
	The issue does not occur if SYSOUT is used.
	SYMPTOMS:
	The following error message will be produced when MIM is shut
	down or is restarted with the LOADLIB REFRESH command:
	IEC999I IFGOTCOA,IFGOTCOB,mim,mim,DEB ADDR=xxxxxx-1,DSN =
	dsname/NULLFILE.
	An SC03 Abend and SVC dump may also be produced.
	IMPACT:
	No impact other than SVC dump processing.
	CIRCUMVENTION:
	Use SYSOUT on the ADDLOG command.
	PRODUCT(S) AFFECTED:
	CA MULTI-IMAGE MANAGER Release 12.5
	Related Problem:
	MIM 15259
	(C) 2022 Broadcom Inc and/or its subsidiaries; All rights reserved
	R00153-BTD125
	DESC(IEC9991 ERROR MESSAGE DURING MIM SHUTDOWN).
	++VER (Z038)
	FMID (CBTDC50)
	PRE (LU04915 S005675)
	SUP (LT05137)
	501 (1105157)

MIM Resource Sharing 12.5 CA RS 2204 - PTF LU05244 Details

LU05244 M.C.S. ENTRIES = ++PTF (LU05244) MIM CTC I/O DELAY		
MIM CTC I/O DELAY		
MIM CTC I/O DELAY		
IIII ete 170 bibili		
PROBLEM DESCRIPTION:		
MIM does not clear validation bits in control blocks which		
represent the CTCPATH statements. The clearing should occur		
when the local system receives an initial handshake from an		
external system where MIM is starting. This can cause MIM to		
send an I/O on a CTC device that is not allocated externally.		
The issue was surfaced when MIM was restarted on a different		
CPU which was using different CTC addresses.		
SYMPTOMS:		
There are 3 known symptoms:		
> VCF delay when trying to migrate from a physical control file to a virtual control file. (COMMUNICATON=CTCDASD)		
For example:		
MIMO200W VCF ACCESS DELAYED - MASTER=SYSA		
> The DISPLAY PATH command may show a delayed WRITMAST I/O such as:		
MIMO176 MIM PATH DISPLAY:		
LAST RESTART AT 12:39:24 ON 2022.016		
DEV SYSTEM STATE IO-STAT READS WRITES ERR TIME/RSV		
N/A SYSB LOCAL 0 0 0.000064		
187A SYSA USABLE BUSY 20 20		
WRITMST		
> MIMO230 MIH TERMINATED I/O ON DEVICE dddd CC=74		
STATUS=0006 SENSE=0000		
IMPACT:		
If the VCF delay occurs, MIM will not process global enqs,		
tape allocations, or cross-system commands/messages.		
CIRCUMVENTION:		
Determine which CTCs are usable/online.		
Rearrange the order of the devices on the CTCPATH statement,		
putting the usable/online devices first in the list.		
Restart MIM.		
PRODUCT(S) AFFECTED:		
CA MULTI-IMAGE MANAGER Release 12.5		
Related Problem:		
MIM 400 (C) 2022 Broadcom Inc and/or its subsidiaries; All rights reserved		
R00154-BTD125		
NOOTS4 BIBIES		
DESC(MIM CTC I/O DELAY).		
++VER (Z038)		
FMID (CBTDC50)		
PRE (LU04915 R091267 S004131 S005399 S011557 S012114)		
SUP (LT05244 S009993 ST09993)		
MCS LU01493 STARTS ON PAGE 0002		
MCS LU03454 STARTS ON PAGE 0003		
MCS LU04830 STARTS ON PAGE 0004		
MCS LU05137 STARTS ON PAGE 0006		
MCS LU05244 STARTS ON PAGE 0007		

MIM Resource Sharing 12.5 CA RS 2204 Product/Component Listing

Product Family	Product	Release
Systems Management	CA MULTI-IMAGE MANAGER	12.05.00
1	The CA RS 2204 Product/Component Count for this release is 1	

CA RS Level	Service	FMID
CAR2204	LU05244	CBTDC50
	LU05137	CBTDC50
	LU04830	CBTDC50
	LU03454	CBTDC50
	LU01493	CBTDC50
CAR2203	LU04915	CBTDC50
CAR2201	LU03655	CBTDC50
CAR2112	LU02532	CBTDC50
CAR2109	LU01392	CBTDC50
CAR2108	LU02013	CBTDC50
CAR2107	LU01570	CBTDC50
CAR2106	S015686	CBTDC50
	LU01409	CBTDC50
CAR2104	LU00471	CBTDC50
CAR2103	LU00164	CBTDC50
	LU00085	CBTDC50
CAR2101	S015800	CBTDC50
CAR2011	S014793	CBTDC50
CAR2008	S013898	CBTDC50
	S013799	CBTDC50
	S013054	CBTDC50
	S012114	CBTDC50
CAR2007	S012844	CBTDC50
	S011978	CBTDC50
CAR2004	S012077	CBTDC50
	S011557	CBTDC50
	S011512	CBTDC50
CAR2002	S011593	CBTDC50
	S011516	CBTDC50
	S010843	CBTDC50
CAR2001	S011259	CBTDC50
	S011206	CBTDC50
CAR1912	S010693	CBTDC50
CAR1911	S010628	CBTDC50
	S010614	CBTDC50
	S010610	CBTDC50
	S010324	CBTDC50
	S010280	CBTDC50
	S010274	CBTDC50
CAR1910	S009993	CBTDC50
CAR1907	S008688	CBTDC50
	S008597	CBTDC50
	S008521	CBTDC50
CAR1906	S008551	CBTDC50
	S008268	CBTDC50
CAR1905	S008194	CBTDC50
	S008094	CBTDC50

CAR1904 S	5007634 5007592 5007211 5007723	CBTDC50 CBTDC50
CAR1904 S	5007211	
CAR1904 S		CBTDC50
\$	5007723	
		CBTDC50
	5007657	CBTDC50
CAR1902 S	5007134	CBTDC50
5	5007087	CBTDC50
CAR1901 S	5006020	CBTDC50
CAR1812 S	5006490	CBTDC50
5	8006306	CBTDC50
5	5006191	CBTDC50
CAR1811 S	5006019	CBTDC50
5	5005973	CBTDC50
5	5005956	CBTDC50
5	005675	CBTDC50
5	5005498	CBTDC50
CAR1810 S	5005399	CBTDC50
CAR1808 S	5004532	CBTDC50
5	5004180	CBTDC50
CAR1807 S	5004131	CBTDC50
CAR1805 S	5001314	CBTDC50
S	5001276	CBTDC50
5	5001264	CBTDC50
CAR1804 S	5000533	CBTDC50
CAR1803 S	5000406	CBTDC50
5	5000122	CBTDC50
CAR1802 F	R099744	CBTDC50
CAR1712 F	R098854	CBTDC50
F	RO98829	CBTDC50
CAR1711 F	R098592	CBTDC50
F	RO98490	CBTDC50
F	RO98456	CBTDC50
CAR1710 F	RO97898	CBTDC50
F	RO97890	CBTDC50
F	R097775	CBTDC50
CAR1709 F	RO97771	CBTDC50
F	RO97770	CBTDC50
F	R097761	CBTDC50
F	RO97760	CBTDC50
CAR1707 F	R096805	CBTDC50
F	R096726	CBTDC50
F	R096602	CBTDC50
F	R096423	CBTDC50
F	RO96418	CBTDC50
F	R096406	CBTDC50
F	R096362	CBTDC50
F	RO95874	CBTDC50

CA RS Level	Service	FMID
CAR1705	R095758	CBTDC50
	R095526	CBTDC50
	R095495	CBTDC50
	R095227	CBTDC50
CAR1704	R095194	CBTDC50
	R095190	CBTDC50
	R094832	CBTDC50
	R094797	CBTDC50
CAR1703	R094688	CBTDC50
	R094446	CBTDC50
CAR1702	R093950	CBTDC50
	R093204	CBTDC50
CAR1701	R093502	CBTDC50
	R093387	CBTDC50
	R093172	CBTDC50
	R092792	CBTDC50
	R092461	CBTDC50
	R092131	CBTDC50
CAR1612	R092579	CBTDC50
	R092220	CBTDC50
	R092065	CBTDC50
	R092034	CBTDC50
	R092033	CBTDC50
	R092025	CBTDC50
	R091444	CBTDC50
	R091267	CBTDC50
	R090940	CBTDC50
	R090884	CBTDC50
	R090825	CBTDC50
	R090796	CBTDC50
	R090790	CBTDC50
	R090745	CBTDC50
	R090647	CBTDC50